

# Surface Water Management Challenges at the Grum Sulphide Cell (GSC) Cover, Faro Mine Complex, Yukon

Dustin Rainey, Ph.D. Geol. I.T. Project Manager - Yukon Government

Dec 1, 2011


# **Contributors + Collaborators**


- Yukon Government Assessment
   & Abandoned Mines, Department
   of Energy, Mines & Resources
- Government of Canada AANDC
- Ross River Dena Council
- Liard First Nation
- Selkirk First Nation
- Town of Faro
- SRK
- DES
- Pelly Construction
- Tim Moon Construction
- Merit Consultants
- Brodie Consulting
- YES Surveyors

- Zero Energy Institute
- Western Tank and Liner
- Boreal Engineering
- Chilkoot Geological Engineers
- EDI Environmental Dynamics
- BGC Engineering
- Gomm Environmental Engineering
- Superior Plastics
- Applied Soil Water Technologies
- Conestoga-Rovers & Associates
- Stratos
- RFP Solutions
- Common Ground Mediation and Consulting
- Environment Canada

# **Outline**


- Faro Mine Complex Background
- GSC Cover Construction Design Rationale
- 2010 Construction
- Freshet 2011
- 2011 Construction
- Future Management of GSC Surface Water
- Lessons Learned

















































# \$13 million later And then it snowed...



# YUKON NEWS

### Faro struggling to deal with meltwater

By Chris Oke

Wednesday May 25, 2011

Recommend Be the first of your friends to recommend this.

Jeremy Warren/Yukon News



The Faro minesite in July 2008.

# Freshet 2011 – What happened?








# **Toe Berm Erosion**











































## 2011 Work Plan

- Additional studies and investigations
- Erosion repairs and mitigations
- Surface water management upgrades
- · Contaminated seep water management upgrades











































## **Erosion Repairs and Erosion Mitigation**































# Surface Water Management Upgrades




















### Contaminated Seep Water Management Upgrades









#### **Lessons Learned**

- Plan to manage surface runoff for at least one year following construction
- Thoroughly characterize the geochemical nature of your borrow sources
- Take your time. Don't rush. Think the project through.
   Then review...

"Make sure you have somewhere for water to go during strange events."

- Brent

"People grossly underestimate the amount of time and money required to maintain covers."

- Bill



#### Faro Mine Remediation Project Projet d'assainissement de la mine Faro



